FIG. 1A

FIG. 1B 2

FIG. 1C




FIG. 1D




FIG. 1E





FIG. 2A








FIG. 3A




FIG. 3B




FIG. 3C



FIG. 3D




FIG. 5B .37a 13a -37 7 PRESSURIZATION FORCE FIG. 4B S) <u>უ</u> ດ FIG. 5A 14a 13a < FIG. 4A 12,

ហ FIG. 6B 00/ 16a-16 0, FIG. 6A

FIG. 7A




FIG. 7B




FIG. 8A

FIG. 8B




FIG. 8C




FIG. 9




FIG. 10A

FIG. 10B




FIG. 11A

FIG. 11B




FIG. 12A 41 40b - 40c 32 - 40 40a -12-32a 0 - 39 47 - 38 FIG. 12B

40c -FIG. 13A 41 40b 40a -36 12-35a 35 42 -FIG. 13B

FIG. 14




FIG. 15 PRIOR ART

